## Work Order (Bid Form)

WO	RK	ORD	ER	INF	ORMA	TION

Work Order Name:

Work Order Type: Weatherization Audit Name: HAYWOOD

**CLIENT INFORMATION** 

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0336

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111 Address: 1574 White AVE

Email Address: Henderson, TN

Agency Contact: Oliver, Jerry

Work Phone: Cell Phone: Email Address:

Company Name & Licens	se Number:	
Contractor's Signature:		

## COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-772-9515

Client Name: Client ID:

Work Order (Bid Form)

Report Run On: 5/13/2010

**DOE** Weatherization Assistant

Alt. Client ID: 16016SW-0336

Work Order Name:

Version 8.5.0

Page 1 of 5

## Measures

Measure 1 Infiltration Redctn					Components				
C	omment								
					Estimated	1		Actual	and the terms of t
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Construction Materials/Hardwar e		Seal plumbing box and wall behind washer,. Seal breaker box	Each	1					
2	Labor	Labor	Hour						
3 Construction Materials/Hardwar e		Seal pipes under kitchen sink. Seal door jams on door frame going into laundry room, Seal around heater	Each	1				To Company of the Com	
4	Labor	Labor	Hour						
5	5 Construction Front east bedroom seal around pipe in closet top and bottom. Bathroom seal pipes under sink		Each	1					
6	Labor	Labor	Hour						
_	Other Detail			***************************************			,		
			-			P( pp - pt			1
									W 1777
-				Measure	Sub Total:		]	Sub Total:	
THE REAL PROPERTY AND ADDRESS OF THE AMERICAN PROPERTY AND ADDRESS OF THE ADDRESS	Field Notes:								

Client Name: Client ID:

DOE Weatherization Assistant

Alt. Client ID: 16016SW-0336

Work Order Name:

Report Run On: 5/13/2010

Work Order (Bid Form)

	WH Pipe Insulation			Componen	ts		1	Inspected
Comment			Estimated		Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	Labor	Each	1					
Other Detail	·		,			, <del>,</del>		
			Measur	e Sub Total:		The state of the s	Sub Total:	
Measure 3 DV Comment	WH Tank Insulation			Componen	ts			Inspected
# Material / Labor	Description / Comment	Units	O4.,	Estimated Unit Cost	Total	O#: /	Actual Unit Cost	Total
Hot Water     Equipment	DHW Tank Insulation	Each	<b>Qty</b> 1		IOLAI	Qty		iotai
2 Labor	Labor	Each	1	To a contract of the contract		100		
Other Detail								
						Transcore and transcore		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Client Name: Client ID:

Alt. Client ID: 16016SW-0336

Work Order (Bid Form)

Work Order Name: Report Run On: 5/13/2010

Page 3 of 5

Measure 4 CO	Monitor is Needed			Componen	ts			Inspecte
Comment								
			Estimated		Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety     Items	CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
	A STATE OF THE PROPERTY OF THE							
				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Field Notes:								
	sureRelief Piping Need	led		Componen	ts			Inspecte
Measure 5 Pres	sureRelief Piping Need	led		Componen	ts		ı	Inspecte
Measure 5 Pres	sureRelief Piping Need	led		Componen Estimated			Actual	Inspecte
Measure 5 Pres	sureRelief Piping Need Description / Comment	led <i>Unit</i> s	Qty	-		Qty		Inspecte Total
Measure 5 Pres Comment  Material / Labor			ama la la la la company a la managama de la managam	Estimated		Qty	Actual	
Measure 5 Pres Comment  Material / Labor  Health and Safety Items	Description / Comment	Units	Qty	Estimated		Qty	Actual	
Measure 5 Pres Comment  Material / Labor Health and Safety Items Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
Measure 5 Pres Comment  Material / Labor Health and Safety	Description / Comment Pressure relief piping	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
Measure 5 Pres Comment  Material / Labor Health and Safety Items Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	<b>Qty</b> 1	Estimated		Qty	Actual	
Measure 5 Pres Comment  Material / Labor Health and Safety Items Labor	Description / Comment Pressure relief piping	Units Each Hour	Qty 1 1	Estimated			Actual	

Client Name: Client ID:

Alt. Client ID: 16016SW-0336

Work Order (Bid Form)

Work Order Name: Report Run On: 5/13/2010

Page 4 of 5

Measure 6 Smoke Detector is Needed			Componen	ts	Inspected		
Comment							
		****	Estimated			Actual	
# Material / Labor Descripti	on / Comment Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Smoke c Items	etector Each	1					
2 Labor Labor	Hour	1				The state of the s	
Other Detail	www.www.www.www.www.www.www.ww.		,				
		Measur	e Sub Total:			Sub Total:	
Field Notes:		*****					
		resident of the lates in model that chief of the state of the	ul adala di Lamandal da mi Empira Amerika na kantan da mangan kantan mangan kantan sa sa mangan kantan sa sa m				
	Work	Order Gra	nd Total:		Gran	d Total:	

Client Name: Client ID:

Alt. Client ID: 16016SW-0336

Report Run On: 5/13/2010